



Baby Lock Ellure PLUS (Model BLR3) Software Update Version 1.11

May 2013




Introduction

If the software version of your Ellure PLUS (Model BLR3) is earlier than version 1.11, an update program is now available for download to improve its performance.

Version 1.11 update will provide the following changes:

1. Fixed the situation where the machine may reboot when loading a particular embroidery pattern in the embroidery card BLEC-32.

To confirm the software version of your BLR3

1. Press the power switch to turn on your machine. The LCD screen comes on.
2. Touch anywhere on the initial opening screen.
3. Touch  /  (Settings key) at the bottom of the LCD display. The Settings screen appears.
4. Touch  (Previous page key) at the bottom of the LCD display.
5. The machine's software version number is displayed on the LCD.



6. If the version shown on your machine is already version 1.11 or later, it will not be necessary to update your machine with the program on this page.



How to download the update program

1. Create a temporary folder (ex. C:\Temp) on your computer to save the update program file to be downloaded.
2. Click the "DOWNLOAD FILE" below.
3. Select the previously created temporary folder (ex. C:\Temp) where the downloaded file should be stored.
4. Download the file.

[Download FILE](#) (UP5 File size: 3.18 MB)

How to update your machine's software

You can use USB media and a computer to download software updates for your sewing machine. Follow the procedure described in the instruction manual.

[Instruction PDF](#) (File size: 64 KB)

*** * * NOTE * * ***

- When using USB media to update the machine's software, check that no data other than the update file is saved on the USB media being used.



Ellure PLUS (Model BLR3) Update History

Version 1.10 update provided the following changes:

- Your embroidery machine will now be able to read your design file(s) if they have been saved within a folder on a USB flash drive (USB flash memory).

** The machine will not be able to read a folder within a folder.*

- For details about using the new features, refer to the following description.

[New Features of Version 1.10](#) (PDF File size: 91KB)